

# Oil Field Environmental Incident Summary

**Incident:** 20160124122304      **Date/Time of Notice:** 01/24/2016 12:23  
**Responsible Party:** CONTINENTAL RESOURCES, INC.  
**Well Operator:** CONTINENTAL RESOURCES, INC.  
**Well Name:** BRADAC CTB  
**Field Name:** CEDAR HILLS      **Well File #:**  
**Date Incident:** 1/23/2016      **Time Incident:** 13:00      **Facility ID Number:** 413779-02  
**County:** BOWMAN      **Twp:** 132      **Rng:** 106      **Sec:** 29      **Qtr:** NE NE  
**Location Description:** Pasture adjacent to flowline ROW.

**Submitted By:** Patrick Skillestad      **Received By:**  
**Contact Person:** Patrick Skillestad  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Pasture      **Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	4	Barrels	4	Barrels	4	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 12/7/2016      **Clean Up Concluded:** 1/27/2016

**Risk Evaluation:**

None

**Areal Extent:**

75 ft x 120 ft

**Potential Environmental Impacts:**

Topsoil in pasture.

**Action Taken or Planned:**

Contaminated soil will be removed and flowline will be repaired.

**Wastes Disposal Location:** Little Missouri Special

**Agencies Involved:**

**Updates**

---

**Date:** 1/25/2016    **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release impacted area off location. Followup is required.

---

**Date:** 2/11/2016    **Status:** Inspection

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Pipeline release CORRECT location: N 46.26358 W 104.00130.

Pipeline excavation is already backfilled. The area is 20 X 20 feet. I suggest returning in the summer months to see if vegetation has grown over site. Photos in report folder.

---

**Date:** 6/3/2016    **Status:** Inspection

**Author:** Sues, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Visited the site on 4/26 at 4:27 p.m. The impacted area had still not revegetated. Soil samples were collected from the site and submitted to the NDDoH laboratory for Group 190 analysis. Waiting on results. More follow-up will be needed to verify vegetation growth.